



PROJECT NAME :

Oakland Cemetery Bell Tower
Building Forensics and Thermography
Atlanta, Georgia

PROJECT DETAILS :

The Oakland Cemetery Bell Tower, circa 1899, suffered internal plaster damage as a potential result of moisture presence within the building envelope. The restoration manager requested assistance from BioPure to investigate the problem.

SCOPE OF SERVICES :

BioPure undertook the investigation of the Bell Tower primarily using thermal imaging to determine locations where moisture was present. The survey confirmed the concerns of the Cemetery Restoration team that moisture had made its way into the building, resulting in delamination of the original plaster work. BioPure provided a report identifying areas of moisture damage, as well as likely causes.

For more information on this project and others, please visit www.biopure-consulting.com or call 404-817-9505 to schedule a consultation.

